SAFETY ALERT

The below information has been issued on behalf of the EFFC to make others aware of the potential risks and possible precautions to take in order to avoid these.



| Date/Time of Incident: |
|------------------------|
|------------------------|

28/10/2020

Type of Incident:

Working at height.

Nature of Incident/Injury:

Danger in default.

Details of Incident:

The Liebherr 53 K fast-erecting crane was erected. In the course of the erection, an employee climbed onto the crane (approx. 20 m high) without being secured and without consulting his foreman. The work was stopped immediately.



Action Taken, Lessons Learnt: An evaluation must be in place. A valid operating instruction must be in place. The employee must be demonstrably instructed with PPE against falls.